

## **TEST REPORT**

100 Clemson Research Blvd. Anderson, SC 29625 (864) 656-1094 Fax: (864) 656-1095



## Results of Tests on brick Conducted in accordance with C67/C67M - 24 Standard Test Methods for Sampling and Testing Brick and Structural Clay Tile

## 08/01/2025

Plant:

Sampled Date:

Received Date:

Fired Date:

Sugarcreek

7/15/2025

7/15/2025

7/15/2025

Name: The Belden Brick Company

P. O. Box 430

Sugarcreek, OH 44681

Phone: 330-456-0031

Fax: 330-456-2694 Report Number: 14085-34978

Description: MORA Ceramicas, White Clay No Additive (Face)

Absorption	1	2	3	4	5	Average	Test Date								
24 Hour Cold Water (%) 5 Hour Boiling Water (%) Saturation Coefficient	4.9 8.1 0.61	4.7 8.1 0.58	5.5 8.5 0.64	5.0 8.2 0.61	5.6 8.6 0.65	5.1 8.3 0.62	7/23/2025								
								Compressive Strength	1	2	3	4	5	Average	Test Date
								psi	10,380	10,840	10,820	11,080	9,560	10,540	7/21/2025
IRA (Oven Dried Method)	6	7	8	9	10	Average	Test Date								
g/min/30 in. <sup>2</sup>	10.4	10.9	10.9	10.2	10.8	10.6	7/18/2025								
Efflorescence	11	12	13	14	15		Test Date								
Efflorescence Detection	Not	Not	Not	Not	Not		7/29/2025								
	Effloresced	Effloresced	Effloresced	Effloresced	Effloresced										
Void Area	1	2	3	4	5	Average	Test Date								
Void Area (%	) 24	24	24	24	24	24	7/18/2025								

The brick represented by the test results shown here comply with the physical property requirements of the standards listed below:

ASTM C216 - 24 Standard Specification for Facing Brick (Solid Masonry Units Made From Clay or Shale)

Grade: SW, MW

Catherine Hill, Quality Manager

\*The temperature and humidity of the Bishop Materials Laboratory is constantly kept between 60-90F, and 30-70% RH. The sampling for these tests was done by the customer. These results are specific to the samples tested. A Simple Acceptance Decision Rule was applied when determining the conformity statement shown on this report. Reporting of test results follows the requirements of the appropriate ASTM Test Method. For information on the decision rules or measurement uncertainty, please contact Kathy Hill, BML Quality Manager. This test report shall not be reproduced except in full, without written approval of the laboratory.

Lab Reference: 14085.34978 Page 1 of 1