

TEST REPORT

100 Clemson Research Blvd. Anderson, SC 29625 (864) 656-1094 Fax: (864) 656-1095



Test Date

9/22/2025

Test Date

11/21/2025

Results of Tests on brick Conducted in accordance with C67/C67M - 25 Standard Test Methods for Sampling and Testing Brick and Structural Clay Tile

11/21/2025

3

5.3

6.7

Plant:

Sampled Date:

Received Date:

5.3

6.9

0.78

Fired Date:

Sugarcreek

9/12/2025 9/12/2025

9/12/2025

5

4.9

6.3

0.77

15

Not

Average

5.1

6.6

0.78

Name: The Belden Brick Company

P. O. Box 430

Sugarcreek, OH 44681

Phone: 330-456-0031

Fax: 330-456-2694 Report Number: 14276-35438

Absorption

Efflorescence

Efflorescence Detection

Description: PLT 6 Fireclay & Shale No Additive (Thin)

1

Description.	TET OT Hedday & Chale No Additive (Tillin)

24 Hour Cold Water (%) 5.0 5 Hour Boiling Water (%) 6.4

Saturation Coefficient 0.78 0.78 0.78

11 12 13 14 Not Not Not Not

Effloresced Effloresced Effloresced Effloresced

The brick represented by the test results shown here comply with the physical property requirements of the standards listed below:

2

5.2

6.6

ASTM C1088 - 24 Standard Specification for Thin Veneer Brick Units Made From Clay or Shale Grade: Exterior, Interior

Katherine Hill, Quality Manager

*The temperature and humidity of the Bishop Materials Laboratory is constantly kept between 60-90F, and 30-70% RH. The sampling for these tests was done by the customer. These results are specific to the samples tested. A Simple Acceptance Decision Rule was applied when determining the conformity statement shown on this report. Reporting of test results follows the requirements of the appropriate ASTM Test Method. For information on the decision rules or measurement uncertainty, please contact Kathy Hill, BML Quality Manager. This test report shall not be reproduced except in full, without written approval of the laboratory.

Lab Reference: 14276.35438 Page 1 of 1