

TEST REPORT

100 Clemson Research Blvd. Anderson, SC 29625 (864) 656-1094 Fax: (864) 656-1095



Results of Tests on brick Conducted in accordance with C67/C67M - 24 Standard Test Methods for Sampling and Testing Brick and Structural Clay Tile

07/24/2025

Name: The Belden Brick Company

P. O. Box 430

Sugarcreek, OH 44681

Phone: 330-456-0031

Description:

Fax: 330-456-2694 Report Number: 14065-34932 Plant: Sugarcreek

Sampled Date: 7/11/2025 Received Date: 7/11/2025 Fired Date: 7/11/2025

PLT 2, Shale/Fireclay Spectrum Series Reduced Fire (Thin Brick)

Absorption	1	2	3	4	5	Average	Test Date
24 Hour Cold Water (%)	1.6	1.2	1.3	1.4	1.8	1.4	7/17/2025
5 Hour Boiling Water (%)	2.1	1.4	1.7	1.6	1.8	1.7	
Saturation Coefficient	0.75	0.88	0.76	0.89	0.97	0.85	
Efflorescence	11	12	13	14	15		Test Date
Efflorescence Detection	Not	Not	Not	Not	Not		7/23/2025
	Effloresced	Effloresced	Effloresced	Effloresced	Effloresced		

The brick represented by the test results shown here comply with the physical property requirements of the standards listed below:

ASTM C1088 - 24 Standard Specification for Thin Veneer Brick Units Made From Clay or Shale Grade: Exterior, Interior

Katherine Hill, Quality Manager

*The temperature and humidity of the Bishop Materials Laboratory is constantly kept between 60-90F, and 30-70% RH. The sampling for these tests was done by the customer. These results are specific to the samples tested. A Simple Acceptance Decision Rule was applied when determining the conformity statement shown on this report. Reporting of test results follows the requirements of the appropriate ASTM Test Method. For information on the decision rules or measurement uncertainty, please contact Kathy Hill, BML Quality Manager. This test report shall not be reproduced except in full, without written approval of the laboratory.

Lab Reference: 14065.34932 Page 1 of 1