



TEST REPORT

100 Clemson Research Blvd.
Anderson, SC 29625
(864) 656-1094
Fax: (864) 656-1095
www.brickandtile.org

Results of Tests on brick Conducted in accordance with ASTM C 67-18 Standard Test Methods for Sampling and

Testing Brick and Structural Clay Tile

06/29/2018

Name:	The Belden Brick Company P. O. Box 430 Sugar creek , OH 44681	Plant:	Sugarcreek	*Temperature:	60 - 90F
Phone:	330-456-0031	Report Number:	8253-18890	*Humidity:	30% - 70%
Fax:	330-456-2694	Received Date:	05/29/2018		
		Sampled Date:	05/29/2018		
		Lot:			
		Product Code:			

Sample Description: PLT 4, SHALE & FIRECLAY NO ADDITIVE

							Test Date	
Absorption		1	2	3	4	5	Average	
24 Hour Submersion in Cold Water (%)		3.52	2.68	3.19	3.13	4.57	3.42	06/01/2018
5 Hour Submersion in Boiling Water (%)		4.50	3.25	4.10	4.07	5.65	4.31	
Saturation Coefficient (Ratio of 24H to 5H)		0.78	0.83	0.78	0.77	0.81	0.79	
Compressive Strength		1	2	3	4	5	Average	
	<i>psi</i>	18,362	16,101	24,146	21,105	13,900	18,723	06/01/2018
	<i>MPa</i>	126.6	111.0	166.5	145.5	95.8	129.1	
Efflorescence		11	12	13	14	15		
		Not Effloresced	Not Effloresced	Not Effloresced	Not Effloresced	Not Effloresced		06/11/2018
IRA (Oven Dried Method)		6	7	8	9	10	Average	
	<i>g/min/30 in.²</i>	5.6	4.3	5.6	5.2	9.6	6.1	06/13/2018
Average % Void		16.6						06/08/2018

The brick represented by the test results shown here comply with the physical property requirements of the standards listed below:

ASTM C 216 - 17a Standard Specification for Facing Brick (Solid Masonry Units Made From Clay or Shale)

Grade: SW, MW

Michael Walker, Quality Manager

**The temperature and humidity of the Bishop Materials Laboratory is constantly kept between 60 -90F, and 30-70% RH*

The results shown above apply only to the samples tested, which are provided by the customer.

This test report shall not be reproduced except in full, without written approval of the laboratory.